



3US__

^

5

Decay, stormy weather blamed for collapse of Allston facade

















PAT GREENHOUSE/GLOBE STAFF

Long-term deterioration and stormy weather were blamed for the sudden collapse of the facade of an Allston building Sunday afternoon that injured two people.

By Matt Rocheleau

GLOBE STAFF NOVEMBER 09, 2018

Long-term deterioration and stormy weather were blamed for the <u>sudden collapse</u> of the facade of an Allston building Sunday afternoon that injured two people, according to a report by structural engineers that the city released Friday.

ADVERTISING

The report by engineers at Hanover-based R.J. Freel Associates, who conducted an onsite inspection the day after the collapse, found evidence that the building's facade had deteriorated, a problem that "could have been caused by water infiltration and expansion caused by the freeze/thaw cycle." Strong winds and rain that hit the area during the weekend of the collapse and the weekend prior may have triggered the incident, the report said. It suggested the parapet was strained as winds blew into a large sign anchored into it above the Common Ground restaurant. ADVERTISEMENT The city requires facades to be inspected on buildings that are 70 feet or taller every five years. Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
The report by engineers at Hanover-based R.J. Freel Associates, who conducted an onsite inspection the day after the collapse, found evidence that the building's facade had deteriorated, a problem that "could have been caused by water infiltration and expansion caused by the freeze/thaw cycle." Strong winds and rain that hit the area during the weekend of the collapse and the weekend prior may have triggered the incident, the report said. It suggested the parapet was strained as winds blew into a large sign anchored into it above the Common Ground restaurant. ADVERTISEMENT The city requires facades to be inspected on buildings that are 70 feet or taller every five years. Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
The report by engineers at Hanover-based R.J. Freel Associates, who conducted an onsite inspection the day after the collapse, found evidence that the building's facade had deteriorated, a problem that "could have been caused by water infiltration and expansion caused by the freeze/thaw cycle." Strong winds and rain that hit the area during the weekend of the collapse and the weekend prior may have triggered the incident, the report said. It suggested the parapet was strained as winds blew into a large sign anchored into it above the Common Ground restaurant. ADVERTISEMENT The city requires facades to be inspected on buildings that are 70 feet or taller every five years. Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
The report by engineers at Hanover-based R.J. Freel Associates, who conducted an onsite inspection the day after the collapse, found evidence that the building's facade had deteriorated, a problem that "could have been caused by water infiltration and expansion caused by the freeze/thaw cycle." Strong winds and rain that hit the area during the weekend of the collapse and the weekend prior may have triggered the incident, the report said. It suggested the parapet was strained as winds blew into a large sign anchored into it above the Common Ground restaurant. ADVERTISEMENT The city requires facades to be inspected on buildings that are 70 feet or taller every five years. Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
The report by engineers at Hanover-based R.J. Freel Associates, who conducted an onsite inspection the day after the collapse, found evidence that the building's facade had deteriorated, a problem that "could have been caused by water infiltration and expansion caused by the freeze/thaw cycle." Strong winds and rain that hit the area during the weekend of the collapse and the weekend prior may have triggered the incident, the report said. It suggested the parapet was strained as winds blew into a large sign anchored into it above the Common Ground restaurant. ADVERTISEMENT The city requires facades to be inspected on buildings that are 70 feet or taller every five years. Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
The report by engineers at Hanover-based R.J. Freel Associates, who conducted an onsite inspection the day after the collapse, found evidence that the building's facade had deteriorated, a problem that "could have been caused by water infiltration and expansion caused by the freeze/thaw cycle." Strong winds and rain that hit the area during the weekend of the collapse and the weekend prior may have triggered the incident, the report said. It suggested the parapet was strained as winds blew into a large sign anchored into it above the Common Ground restaurant. ADVERTISEMENT The city requires facades to be inspected on buildings that are 70 feet or taller every five years. Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
The report by engineers at Hanover-based R.J. Freel Associates, who conducted an onsite inspection the day after the collapse, found evidence that the building's facade had deteriorated, a problem that "could have been caused by water infiltration and expansion caused by the freeze/thaw cycle." Strong winds and rain that hit the area during the weekend of the collapse and the weekend prior may have triggered the incident, the report said. It suggested the parapet was strained as winds blew into a large sign anchored into it above the Common Ground restaurant. ADVERTISEMENT The city requires facades to be inspected on buildings that are 70 feet or taller every five years. Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
The report by engineers at Hanover-based R.J. Freel Associates, who conducted an onsite inspection the day after the collapse, found evidence that the building's facade had deteriorated, a problem that "could have been caused by water infiltration and expansion caused by the freeze/thaw cycle." Strong winds and rain that hit the area during the weekend of the collapse and the weekend prior may have triggered the incident, the report said. It suggested the parapet was strained as winds blew into a large sign anchored into it above the Common Ground restaurant. ADVERTISEMENT The city requires facades to be inspected on buildings that are 70 feet or taller every five years. Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
The report by engineers at Hanover-based R.J. Freel Associates, who conducted an onsite inspection the day after the collapse, found evidence that the building's facade had deteriorated, a problem that "could have been caused by water infiltration and expansion caused by the freeze/thaw cycle." Strong winds and rain that hit the area during the weekend of the collapse and the weekend prior may have triggered the incident, the report said. It suggested the parapet was strained as winds blew into a large sign anchored into it above the Common Ground restaurant. ADVERTISEMENT The city requires facades to be inspected on buildings that are 70 feet or taller every five years. Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
The report by engineers at Hanover-based R.J. Freel Associates, who conducted an onsite inspection the day after the collapse, found evidence that the building's facade had deteriorated, a problem that "could have been caused by water infiltration and expansion caused by the freeze/thaw cycle." Strong winds and rain that hit the area during the weekend of the collapse and the weekend prior may have triggered the incident, the report said. It suggested the parapet was strained as winds blew into a large sign anchored into it above the Common Ground restaurant. ADVERTISEMENT The city requires facades to be inspected on buildings that are 70 feet or taller every five years. Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
The report by engineers at Hanover-based R.J. Freel Associates, who conducted an onsite inspection the day after the collapse, found evidence that the building's facade had deteriorated, a problem that "could have been caused by water infiltration and expansion caused by the freeze/thaw cycle." Strong winds and rain that hit the area during the weekend of the collapse and the weekend prior may have triggered the incident, the report said. It suggested the parapet was strained as winds blew into a large sign anchored into it above the Common Ground restaurant. ADVERTISEMENT The city requires facades to be inspected on buildings that are 70 feet or taller every five years. Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
The report by engineers at Hanover-based R.J. Freel Associates, who conducted an onsite inspection the day after the collapse, found evidence that the building's facade had deteriorated, a problem that "could have been caused by water infiltration and expansion caused by the freeze/thaw cycle." Strong winds and rain that hit the area during the weekend of the collapse and the weekend prior may have triggered the incident, the report said. It suggested the parapet was strained as winds blew into a large sign anchored into it above the Common Ground restaurant. ADVERTISEMENT The city requires facades to be inspected on buildings that are 70 feet or taller every five years. Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
The report by engineers at Hanover-based R.J. Freel Associates, who conducted an onsite inspection the day after the collapse, found evidence that the building's facade had deteriorated, a problem that "could have been caused by water infiltration and expansion caused by the freeze/thaw cycle." Strong winds and rain that hit the area during the weekend of the collapse and the weekend prior may have triggered the incident, the report said. It suggested the parapet was strained as winds blew into a large sign anchored into it above the Common Ground restaurant. ADVERTISEMENT The city requires facades to be inspected on buildings that are 70 feet or taller every five years. Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
The report by engineers at Hanover-based R.J. Freel Associates, who conducted an onsite inspection the day after the collapse, found evidence that the building's facade had deteriorated, a problem that "could have been caused by water infiltration and expansion caused by the freeze/thaw cycle." Strong winds and rain that hit the area during the weekend of the collapse and the weekend prior may have triggered the incident, the report said. It suggested the parapet was strained as winds blew into a large sign anchored into it above the Common Ground restaurant. ADVERTISEMENT The city requires facades to be inspected on buildings that are 70 feet or taller every five years. Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
The report by engineers at Hanover-based R.J. Freel Associates, who conducted an onsite inspection the day after the collapse, found evidence that the building's facade had deteriorated, a problem that "could have been caused by water infiltration and expansion caused by the freeze/thaw cycle." Strong winds and rain that hit the area during the weekend of the collapse and the weekend prior may have triggered the incident, the report said. It suggested the parapet was strained as winds blew into a large sign anchored into it above the Common Ground restaurant. ADVERTISEMENT The city requires facades to be inspected on buildings that are 70 feet or taller every five years. Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		in Donald income to all host Topodo
day after the collapse, found evidence that the building's facade had deteriorated, a problem that "could have been caused by water infiltration and expansion caused by the freeze/thaw cycle." Strong winds and rain that hit the area during the weekend of the collapse and the weekend prior may have triggered the incident, the report said. It suggested the parapet was strained as winds blew into a large sign anchored into it above the Common Ground restaurant. ADVERTISEMENT The city requires facades to be inspected on buildings that are 70 feet or taller every five years. Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		inkead invented by Teads
The city <u>requires</u> facades to be inspected on buildings that are 70 feet or taller every five years. Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.	large sign anchored into it above the Common Ground restauran	
Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.	ADVERTISEMENT	
Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New England delivered daily.		
The 10 top local news stories from metro Boston and around New England delivered daily.		
	The city <u>requires</u> facades to be inspected on buildings that are 70) feet or taller every five years.
) feet or taller every five years.
	Get Metro Headlines in your inbox:	
	Get Metro Headlines in your inbox:	
	Get Metro Headlines in your inbox:	
	Get Metro Headlines in your inbox: The 10 top local news stories from metro Boston and around New	

But the single-story Allston building at 75-87 Harvard Ave. was too short to trigger such inspections. For smaller buildings, it's up to the owners to inspect their properties and make repairs when needed.

City records list the property's owner as Moss Realty LLP and the property's manager as Myer Dana and Sons, based in Newton. Officials at those entities and at the Common Ground restaurant did not respond to requests for comment Friday.

The engineering firm's report noted the deterioration of the building's facade may have been difficult to see because "a good portion of these parapets are covered with flashing and some form of waterproofing," the report said.

City officials declined to comment, including about whether there should be more scrutiny of building facades.



On Sunday, the facade of the Allston building plummeted without warning to the sidewalk, trapping one woman under the rubble and seriously injuring her, wounding a man who was with her, and damaging several cars.

Officials have estimated the collapse caused about \$500,000 in damage.

The 12,600-square-foot building was assessed for tax purposes this year as being worth more than \$1.5 million, city records show. It was built in 1920.

City officials said Friday that steps have been taken to clean up debris and remove damaged portions of the building.

More repair work was ongoing. Once that's complete, the building will need another inspection by city officials to determine its structural integrity before it gets approval to reopen.





Officials have not provided updates about the medical condition of the woman who was injured and hospitalized, but a report Boston police filed Sunday said that the initial prognosis was that while she suffered "substantial damage to her hand and legs," her injuries "were not critical."

One witness, Susanne Maher, a nurse practitioner from Needham who helped pull the woman from the rubble, told the Globe previously the woman remained conscious and alert until EMTs arrived.

But Maher said the woman's right hand had been crushed by the debris, and a man who was with the woman said she is a pianist.

"He kept asking if she's going to be able to play again," Maher recalled. "He was clearly heartbroken."

Matt Rocheleau can be reached at matthew.rocheleau@globe.com. Follow him on Twitter @mrochele

Show 1 Comment

SPONSORED BY ALLWAYS HEALTH PARTNERS

Sharon principal placed on administrative leave

Two sisters, one house, and a mystery

How Do Copays, Deductibles, and Out-of-Pocket Maximums Work?

By AllWays Health Partners - Here's a helpful guide to the terms for costs you may encounter as you receive care. More

Top 10 Trending Articles

Viewed	Commented	Shared		
People in open-concept homes are realizing the walls were there for a reason				
Ideas Linda Rodriguez McRobbie: Too old to be president? Science says yes.				
Mass. authorities face steep hurdles in shutting down sex trafficking				
The backyard mechanic who is taking on Tesla				
Here's what NFL free agent market looks like ahead of league's legal tampering period				
Julia Ruth Stevens, Babe Ruth's last surviving child, dies at 102				
Road to Recovery: Drugs took their children, but not their hope that others might be saved				
This week in watching: The fall of 'Arrested Development,' the return of 'Billions,' and the power of punk				
Maybe we need to just let Kyrie be	Kyrie and enjoy the ride			

Priest who used to work in Seekonk church placed on leave for 'inappropriate communications'

Twitter

Google+

More

Decay, stormy weather blamed for sudden collapse of Allston facade - The Boston Globe

ePaper

News in Education

Archives

Privacy policy

Terms of service

Terms of purchase

© 2019 Boston Globe Media Partners, LLC

Work at Boston Globe Media